Shaukiwan Road

1846 - 1847


Stanley Road


1847 - 1848

Pok Fu Lam Conduit

1876 - 1877

22 masonry bridges and aqueducts, 4 drainage culverts






Shaukiwan Road

1846 - 1847

Remains of 3 bridges and 1 drainage culvert found


Pending identification for heritage assessment



14 February 1846

來源:政府檔案處

Source: Government Records Service







Stanley Road


1847 - 1848

Remains of 3 bridges and 3 drainage culverts found Structures are identified for heritage assessment

N123 – Deep Water Bay

N374 – Stanley


赤柱路建造合约 Construction Contracts of Stanley Road





合約第八號 Contract No. 8 20 December 1847

來源:政府檔案處

Source: Government Records Service







THE

SESSIONAL PAPERS

PRINTED BY ORDER

OF

THE HOUSE OF LORDS,

OR PRESENTED BY ROYAL COMMAND,

IN TH

Session 1849.

(12° & 13° VICTORIÆ,)

ARRANGED IN VOLUMES.

Vol. XXXIX.

REPORTS FROM COMMISSIONERS, &c.

(Ten Volumes,)
CONTINUED;


THE SUBJECTS ALPHABETICALLY ARRANGED.

SUBJECT OF THIS VOLUME
Colonial Possessions.

Read from Aberdeen to Stanley, 7 miles. - This road estimated for, Rep. and Est. amount, 4965/. 14s. 1d. (No. 1, of 1847) was intended to have been 15 feet wide throughout, with stone arches and parapet-walls in places where they were most required. Sir J. F. Davis, however, reduced the width to 10 feet and curtailed other works, and only authorized the sum of 27051. 14s. 4d. to be expended; of this sum 3121. 16s. 4d. was expended during the year 1847, the expenditure during the last year being 19221. 12s. 1d. Upon this line are some of the heaviest stone bridges in the island, which considering the Chinese are not in the habit of building such, have been very tolerably executed, and particularly so, as the hot weather and frequent sickness of the overseers prevented their constant attendance thereon. The greater portion of the road was in the hands of the contractors at the time of the typhoon and previous rains, and therefore the expense of repairs fell upon them, but in general the damage was not excessive considering the unconsolidated state of the filling, unfinished drains, &c. Near the south end of the town of Aberdeen for a distance of 100 yards, and in Deep Water Bay for about the same distance, the wash of the sea carried away a considerable portion of the road; the former had been taken off the contractor's hands, and has not yet been repaired; the latter the contractor was obliged to rectify. In sheltered bays on the coast I formed the roads originally 4 feet above the high-water spring tides and 6 feet in other parts, but I now find that not less than 10 feet should be fixed upon for the level of a coast road, and even more then that if it is much exposed. If this road is to be maintained and properly protected, as indeed most of the roads require, there are several works which I would recommend to be executed, viz., a bridge and causeway at the waterfall in Staunton Valley, a paraper-wall on the hill above Deep-water Bay, and a bridge leading to the Sands, parapet-walls in two other places near Repulse Bay, and a bridge there also; these places are either exceedingly dangerous or inconvenient, as the road has either been cut out of the side of the cliff, or a rough retaining wall built, which leaves the drop from the road nearly perpendicular, and in one place the fall is 100 feet. The additional bridges are required, for at high water pedestrians must make a detour to pass the stream, and equestrians must wade or swim their horses over the ford. The details of expenditure during the year being given in full in the usual return, I shall merely remark that the disbursements on the new works in the formation of roads, bridges, and drains have amounted to 32211. 11s. 7d., and remains, exclusive of conviet labour, to the sum of 215l. 2s. 8d. for roads and 186l. 10s. 1d. for bridges.

工務司有關1848年的報告。Report of 1848 by the Surveyor-General. 沿線的石橋是香港島其中最大型的。Upon this line are some of the heaviest stone bridges on the island. 「考慮到承建商缺乏相關經驗以及酷熱天氣及生病監督,這些石橋」建造得相當妥當。(Despite their unfamiliarity and difficulties of supervision due to sickness and hot weather, these stone bridges) have been "very tolerably executed"。

1848 年底的赤柱路狀況(推斷) Conditions of Stanley Road by End of 1848 (Inferred)



赤柱缺道 Stanle Gap Roat 脊髓角道 11號 11 Chung Hom Kok 赤柱電 話機房 馬坑部駿 馬槽 Chun Ma Hang Prison Ma House 馬樓 Chun Ma Hang Ma House 赤柱崗速 Ma Hang Stapley Ma House 馬坑邸 Mound Ma Hana Estate Ma House Stanley Tak House 馬坑 Ma Hang Chun Tak House 龍德苑 Lung Tak Tak House

2021 Stanley Road

Red line: Stanley Road built in 1847-48 is overgrown but identifiable and safe for pedestrian use. Vegetation to be cleared and path improved. Reconfirm and sign post the street name. Reserve alignment of future connection to public roads on east upon redevelopment of Ma Hang Prison.

(HAD/DMW) (LandsD) (PlanD) (DevB)

Red circles: Two masonry bridges and drainage channels are among the remaining features built in 1848. Monument status for remaining features of Stanley Road and re-use as a pedestrian path. (DevB, AMO/AAB)

Blue line: Existing path with stairs from the junction of Chung Hom Kok Road and Stanley Gap Road, to Cape Road. *The path widening.* (WSD) (HAD/DMW)

Black line: Trail connecting with Wilson Trail. An increasing number of hikers make use of the path to get from Wilson Trail bus stop at Stanley Gap Road to Stanley Plaza. This path needs improvements. (HAD/DMW)


Pok Fu Lam Conduit


1876 - 1877

Graded: Gauge basin, tunnel, aqueduct No 9 at Queen Mary Hospital (Appraisal 429)


Remaining: long sections of conduit including original covers, 15 aqueducts, and part of one tank near Seymour Road.


N372 – Remaining sections identified for heritage assessment





The Pok Fu Lam Conduit included 32 aqueducts between Pokfulam Reservoir and the West Point filter beds (near what is now known as the Lung Fu Shan Environmental Education Centre). A recent survey shows that 16 are still in tact. Number 9 is graded as a heritage structure.





















Search Criteria

Slope Number: 11SW-C/R25

List of Slope Maintenance Responsibility Area(s)

1 record(s) found


Slope No.	11SW-C/R25
Location	WITHIN RBL757 NEAR N BOUNDARY
Responsible Lot/Party	RBL757
Maintenance Agent	Not Applicable
Remarks	Not Applicable
	Technical Information











Southern District Office

Will the Southern District Officer and his team supported by the Home Affairs Bureau assume responsibility for coordination with the various government departments to:

- Provide for adaptive re-use and enhancement of the conduit and Stanley Road for pedestrians, including improvement of access;
- 2. Signage to direct and inform visitors of the various features for the entire length of the two roads and the conduit;
- 3. Re-establish the name 'Stanley Road' for the remaining section in Stanley; and
- 4. Ensure the features found are protected.