

HAD – MINOR WORKS PROJECT – TAI PO DISTRICT




TP-DMW108 Demolition of planter at On Cheung Road near Fortune Plaza and
the construction of a rainshelter
拆除安祥路近昌運中心花槽以及加設避雨亭



ARCHITECT/LEAD CONSULTANT
Tom Ip & Partners Architects Engineers &
Development Consultants Limited


SUB – CONSULTANTS
Paul Wong Consulting Engineers Ltd.
Daniel Chan & Associates Ltd.
Earthasia Limited
Hyder Consulting Limited

QUANTITY SURVEYORS & CONTRACT MANAGEMENT CONSULTANTS
Rider Levett Bucknall Limited



位置圖

中電高壓電纜圖





現場情況

