Proposal of improvement works for the uneven pavement and cycle track at Tung Chung Road (Existing Trees at circled area: 78 nos.)

Portion of cycle track with protruding tree roots from roadside trees planted on pavement (about 20 nos. of trees)

Proposed improvement works including:

Option 1 : To narrow portion of cycle track where deck over is not feasible; (TD & HYD)

Option 2 : To deck over portion of affected cycle track; (TD & HYD), in parallel, to raise up railing of the retaining wall; (DSD/ CEDD)

LCSD will arrange appropriate root and crown pruning to facilitate the construction if necessary.

Portion of pavement with protruding tree roots from roadside trees planted on the pavement (about 58 nos. of trees)

Proposed improvement works including:

- (i) To enlarge and integrate existing tree pits into linear kerb planters to provide additional space for tree roots growth; (TD & HYD)
- (ii) To install root barrier along periphery of linear planters be informed to restrict tree roots growth; (TD & HYD)
- LCSD will arrange appropriate root and crown pruning to facilitate the construction if necessary.




Proposal of improvement works for the uneven pavement and cycle track at Tung Chung Road


I) Portion of cycle track with protruding tree roots from roadside trees planted on pavement (about 20 nos. of trees)

















Illustration of proposal
Enlargement and integration of existing tree pits into linear kerb planters






粉嶺樓遊樂場




沙田大會堂





T12 - T13 : Form a planting strip for T12 - T13 - before





190cm is measured from the kerb to the edge 120cm is measured from the trunk of T12 to the edge 110cm is measured from the trunk of T13 to the edge

T12 - T13 - after

