

Photos Record



Photo 1: before



Photo 2: After - Trimming overgrown grass and clearing debris



Photo 3: before



Photo 4: After - Trimming overgrown grass and clearing debris



Photo 5: Before



Photo 6: After - Destroyed suspected rat holes



Photo 7: Before



Photo 8: After - Destroyed suspected rat holes



Photo 9: Clearing debris



Photo 10: Clearing debris



Photo 11: Before



Photo 12: After - Installed wire mesh to prevent drain holes from becoming rat holes.

Location plan

